



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

(801) 538-5340 telephone

(801) 359-3940 fax

(801) 538-7223 TTY

www.nr.utah.gov

Michael O. Leavitt
Governor

Robert L. Morgan
Executive Director

Lowell P. Braxton
Division Director

November 7, 2002

TO: Minerals File

FROM: Doug Jensen, Senior Reclamation Specialist *DJensen*

RE: Site Inspection, Roudabush #1 Mine, Worthen/Williams LLC, M/045/027, Tooele County, Utah

Date of Inspection: November 7, 2002
Time of Inspection: 9:00 a.m.
Conditions: Windy, Cloudy & Windy
Participants: Doug Jensen, Tom Munson, DOGM

Purpose of Inspection:

Site familiarization and review of disturbances at site for bond escalation purposes.

Getting to the site:

Turning south off Main Street of Grantsville on Cooleys Lane attains access to the road into site. Drive south 9.2 miles then turn right on a dirt road for .2 miles then turn right again. Drive this road for ~.3 miles to the site.

Observations:

The site was clean and at the time of the visit there was no mining activity taking place. There were several stockpiles and topsoil piles located on the stockpile area. None of the stockpiles were very large.

There were no areas of concern in the quarry area. An inspection of the highwalls of the quarry did not show any areas of concern. There is one drainage on the south side of the quarry, this area was open and did not show any erosion problems.

There was no equipment located at the site at the time of the inspection. The site was left in good condition when the last crushing campaign was completed.

Conclusions and Recommendations:

One minor problem was noted during the site visit. A stockpile had been placed off the area that had been prepared for this purpose. No soil had been harvested from the area before the pile was placed. Soil is to be harvested within the stockpile area for use when the site is reclaimed.


Pictures were taken of the site; also a GPS map of the present disturbance was made. These items are included with this report.

jb

cc: Robert Worthen, Worthen/Williams LLC w/photos & GPS map
O:\M045-Tooele\M045027-Roudabush\Final\insp-11-7-02.doc

Roudabush #1 Mine

M/045/027




0.3 0 0.3 0.6 Miles

 **Current Disturbance**



This Inspection was performed by DOGM staff on November 7, 2002, South Mountain Quad., Desert Peak East, R5W, T4S, Sw1/4 Sec 14, NW1/4 Sec 23

This product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause some misalignment of data layers.



11/7/2000